

# Service Kit 753-0718

CODE: CP-025


DATE: December 3, 1997

SUBJ: Locking Rod for Log Splitters

- **Problem:** Locking Rod (781-0370A) has been replaced with new locking Rod (781-0690)
- **Cause:** Locking Rod (781-0370A)
- **Solution:** Install Service Kit 753-0718

## Instructions:

1. Remove the old Locking Rod (781-0370A) and hardware from the unit. Discard cotter pins because they will not be needed on new Locking Rod.
2. Install the new Locking Rod (**781-0690**) and replace the washers and the spring from the previous rod. Secure the Locking Rod with (**726-0214**) push cap supplied in the service kit. **See diagram below.**



Service Kit 753-0718 consists of:

Ref No.	Part No.	Description	Qty.
1	781-0690	Locking Rod	1
2	726-0214	Push Cap	1