

# SERVICE KIT

## 753-0552

CODE: SP-132  
 DATE: MARCH 18, 1992  
 SUBJECT: FRONT WHEEL AND DUST  
 CAP REPLACEMENT -  
 MODELS 122-440R THRU  
 122-458R FRONT WHEEL  
 DRIVE SELF-PROPELLED  
 LAWN MOWERS

**PROBLEM:** The front wheels of the mower are difficult to turn.

**CAUSE:** The plastic wheels were molded incorrectly at the wheel hub causing the wheel to be tight when assembled to the mower.

**SOLUTION:** Order and install Service Kit 753-0552. Kit contains two (2) new wheels , new dust caps, and cotter pins.

### INSTRUCTIONS:

1. Remove the front right hand side hub cap.
2. Remove cotter pin, flat washer and wheel from height adjuster pivot plate.
3. Carefully remove "E" ring, 14-tooth spur gear and flat washer from axle.
4. Remove and discard broken dust cap.
5. Install NEW dust cap and wheel in reverse order.
6. Repeat steps 1 through 5 on the left hand side of mower.

### SERVICE KIT 753-0552 CONSISTS OF:

REF. NO.	PART NO.	DESCRIPTION	QTY.
1	714-0111	Cotter pin	2
2	634-0021	Front Wheel	2
3	782-7551	Wheel Dust Cap	2

