

SERVICE KIT

753-0595

753-0596

CODE: R-351

DATE: February 11, 1994

SUBJECT: Replacement Drive Shaft
Assemblies - 600 Series
Lawn Tractor

Service Kit 753-0595 replaces R.H. Drive Shaft part number 711-0943

Service Kit 753-0596 replaces L.H. Drive Shaft part number 711-0942

Kit 753-0595 consists of:

REF.	PART NO.	DESCRIPTION	QTY
1	736-0519	Thrust Washer	1
2	711-1003	R.H. Drive Shaft	1

Kit 753-0596 consists of:

REF.	PART NO.	DESCRIPTION	QTY
1	736-0519	Thrust Washer	1
2	711-1016	L.H. Drive Shaft	1

