

# Service Kit 753-0642

Code: R-367


Date: September 12, 1995

Subject: Replacement Pivot Bar Ass'y  
Model 400/600/700Series Riders.

THIS KIT REPLACES PART NO. 683-0002

Ref. No.	Part No.	Description	Quantity
1	683-0128	Pivot bar Ass'y	1
2	741-0659	Flange Brg. .632" I.D.	4

This kit will replace earlier style pivot bar assemblies. The flange bearings (Part No. 741-0487A) used on the 683-0002 pivot bar will not work on the new assemblies. These bearings must be replaced with the new flange bearings provided in the kit.



Service kit 753-0642 is for a new pivot bar on a 600 series machine. It works unless you have a Yardman machine. If that is the case, the person putting on the pivot bar will not be able to get the flange bearings to sit flush on the pivot bar because the end caps, part #731-1291 on the Yardman, get in the way. Make a note in your Yardman illustrated parts that if they use this kit on a Yardman that they need to change the end caps also to a 731-1291A. That'll work.