


Service Kit 753-0712

CODE: ST-140

DATE: August 29, 1997

SUBJ: Idler brake/bracket replacement.

Service Kit 753-0712 replaces idler brake bracket assembly part number 784-5180B.



Service Kit 753-0712 consists of:

Ref. No.	Part No.	Description	Qty.
1	710-0459	Hex screw-3/8-24 x 1.50	1
2	712-0116	Hex lock nut-3/8-24	1
3	784-5175B	Idler/brake bracket	1

Form No. 770-0816A


Service Kit 753-0712

CODE: ST-140

DATE: August 29, 1997

SUBJ: Idler brake/bracket replacement.

Service Kit 753-0712 replaces idler brake bracket assembly part number 784-5180B.



Service Kit 753-0712 consists of:

Ref. No.	Part No.	Description	Qty.
1	710-0459	Hex screw-3/8-24 x 1.50	1
2	712-0116	Hex lock nut-3/8-24	1
3	784-5175B	Idler/brake bracket	1

Form No. 770-0816A