

Service Kit 753-0721

CODE: PM-269

DATE: December 3, 1997

SUBJ: Wheel replacement on Airap
push mowers.


Problem: Push mower wheels (706-10333) will now be replaced with new wheels (**734-1779**).

Cause: Push mower wheels (706-10333) have been discontinued.

Solution: Install Service Kit **753-0721**.

Instructions:

1. Remove all four wheels (706-10333) from unit.
2. Replace all four wheels with new wheels (**734-1779**) provided in service kit. Use existing hardware when reattaching new wheels to unit.



Service Kit 753-0721 consists of:

Ref. No.	Part No.	Description	Qty.
1	734-1779	7" wheel assembly	4