

# SERVICE KIT

CODE

CP-031

DATE


September 16, 1998

SUBJECT

Tongue tube  
Replacement

## 753-0844

Install Service Kit 753-0844 when replacing part number 781-0691



Service Kit 753-0844 consists of:

<u>Reference Number</u>	<u>Part Number</u>	<u>Description</u>	<u>Quantity</u>
1	781-0398-0637	Beam Support Assembly	1
2	781-0680-0637	Tongue Tube	1
3	726-0214	Push cap	1

FORM No. 770-1548A