

Service Kit 753-0883

CODE: RT-139

DATE: February 15, 2000

SUBJECT: Spur Gear Replacement

MODELS AFFECTED: Tillers model 430 through 448
produced prior to 1997

Service Kit 753-0883 applies to all tiller models 430 through 448 produced prior to 1997. This kit should be used when replacing the 44 tooth spur gear (717-0863) or the 55 tooth spur gear (717-0858). Contents of the kit are listed below.

NOTE: Chain case requires 30 oz. of Benelene 920 Grease. Order 4 of part # 737-0300A (8 oz. tube).

Reason is due to BOTH PARTS going NLA.

REF. NO.	PART NO.	QTY.	DESCRIPTION
1	717-1470	1	Spur Gear Assembly; 44T / 11T
2	717-1471	1	Spur Gear; 44T

