

# Service Kit 753-0889

CODE: ST-159

DATE: August 4, 2000

SUBJECT: Gear Housing Replacement

Use this Service Kit when replacing either part number 717-0297 or 717-0298.

REF NO.	PART NO.	QTY.	DESCRIPTION
1	710-1260A	7	Hex Screw
2	618-0246	1	Gear Housing Assembly RH
3	618-0247	1	Gear Housing Assembly LH

**Note:** Hex screws should be torqued to between 19 and 22 foot pounds.

