

# Service Kit 753-0901

CODE: ST-165

DATE: March 7, 2001

SUBJECT: Pulley Replacement

MODELS AFFECTED: Two stage snow throwers with pulley number 756-0572

Use this Service Kit when replacing Auger Drive pulley part number 756-0572

REF. NO.	PART NO.	QTY	Description
1	756-0967	2	Auger Drive Pulley
2	710-0627	1	Hex Bolt
3	736-0505	1	Flat Washer
4	736-0242	1	Bell Washer
5	748-0360	1	Pulley Adapter

**Note:** Not all models affected by this service kit will use both pulleys. Also, belts are shown for reference only, they are not included in the kit.

