

Service Kit 753-0904

CODE: R-465

DATE: August 13, 2001

SUBJECT: Deck Lift Shaft Assembly

MODELS AFFECTED: 600 and 800 Series Pedal Drive Step Thru Frame Models w/ 42", 46" and 50" Decks

Use this service kit when Deck Drive Belt loss is experienced while cutting in the lowest cutting position. The lowest cutting height is approximately 3/4 inches. Installation of this kit will result in correcting the lowest cutting height from 3/4 inch to 1 1/2 inches in accordance with engineering design. The corrected cutting range will then be 1 1/2 to 3 1/2 inches.

Typical Installation Time: 60 minutes



Service Kit Contents

REF. NO.	PART NUMBER	QTY	DESCRIPTION
1	746-1144	2	Lift Cable, 15.62" Long
2	683-0197B	1	Lift Shaft Assembly

Lift Cable Location:

When connecting the Lift Cables to the Lift Shaft Assembly ensure the correct hole is used in accordance with the hole identification stamped in each cable attach bracket and Figure 1.

Position "46LT" is for Lawn Tractors w/ 46" deck and either manual or electric PTO.

Position "42" (middle hole) is for Lawn Tractors w/ 42" deck and manual PTO only.

Position "GT" is for all Garden Tractors w/ 46" and 50" decks and either manual or electric PTO.



Figure 1