

SERVICE KIT

753-0580

CODE: T-108
DATE: JUNE 3, 1993
SUBJECT: REPLACEMENT KIT FOR
725-0758 SPRING SWITCH

Part number 725-0758 will be replaced by service kit number 753-0580.

REF. NO.	PART. NO.	DESCRIPTION	QTY.
1	725-1644	Spring Switch	1
2	726-0320	Insulator Plate	1
3	710-0227	Screw	2