


SERVICE KIT 753-0587

CODE: T-113 / W-070
DATE: December 16, 1993
SUBJECT: Muffler Heat Shield - Model 998 Tractors

Service kit 753-0587 is a heat shield for the muffler for the model 998 tractor with a 18 HP Vanguard engine. Install the heat shield as shown below, using the hardware provided with the kit.

KIT 753-0587 CONSISTS OF:

REF.	PART NO.	DESCRIPTION
1	710-3030	Hex Bolt 7/16-14 x .75" Lg.
2	736-0171	Lock Washer 7/16" I.D.
3	783-0237	Muffler Heat Shield



Tools Required for Installation:

- (1) 11/16" Wrench
- (1) 10 MM Socket Wrench

To Install:

Remove right hand side panel. Install kit as shown. Replace side panel.

Allowable Repair Time Under Warranty - 10 Minutes
Travel Allowance - \$15.00