

Service Kit 753-0588


CODE: SP-146

DATE: August 8, 1998

SUBJ: Blade Adapter Kit- 1.19"
Adapter

Service Kit 753-0588 Consists of:

Ref. No.	Part No.	Description
1	748-0376C	Blade Adapter
2	736-0524A	Blade Bell Support
3	710-1044	Hex Bolt 3/8-24 x 1.5" Lg.



Form No. 770-8708J
(R980320)

Service Kit 753-0588


CODE: SP-146

DATE: August 8, 1994

SUBJ: Blade Adapter Kit- 1.19"
Adapter

Service Kit 753-0588 Consists of:

Ref. No.	Part No.	Description
1	748-0376C	Blade Adapter
2	736-0524A	Blade Bell Support
3	710-1044	Hex Bolt 3/8-24 x 1.5" Lg.



Form No. 770-8708J
(R980320)