



Service Kit 753-0661

Code: RT-126

Date: May 21, 1996

Subject: Drive Shaft 410/420 Tillers

THIS KIT REPLACES PART NUMBER 711-0952 (DRIVE SHAFT).



Ref. No.	Part No.	Description	Quantity
1	711-1087	Drive Shaft	1
2	732-0614	Wire Ring	1
3	770-0304L	Kit Sheet	1