

# SERVICE KIT

CODE: CP-024

DATE: April 18, 1997

753-0688

753-0696

753-0697

753-0699

SUBJ: Replacement cylinders for  
vertical logsplitters 1993 to  
1996

Service Kit 753-0688 replaces 4" dia. cylinder part number 718-0245.

Service Kit 753-0688 consists of:

Ref. No.	Part No.	Description	Qty.
1	718-0307	Cylinder-4" dia.	1
2	727-0471	Pressure tube	1

Service Kit 753-0696 replaces 4.50" dia. cylinder part number 718-0246.

Service Kit 753-0696 consists of:

Ref. No.	Part No.	Description	Qty.
1	718-0306	Cylinder-4.50" dia.	1
2	727-0471	Pressure tube	1

Service Kit 753-0697 replaces 5" dia. cylinder part number 718-0247.

Service Kit 753-0697 consists of:

Ref. No.	Part No.	Description	Qty.
1	718-0313	Cylinder-5" dia.	1
2	727-0471	Pressure tube	1

Service Kit 753-0699 replaces 4.25" dia. cylinder part number 718-0262.

Service Kit 753-0699 consists of:

Ref. No.	Part No.	Description	Qty.
1	718-0312	Cylinder-4.25" dia.	1
2	727-0471	Pressure tube	1

**SEE REVERSE SIDE FOR ILLUSTRATION**



AVAILABLE COLORS

Charcoal	718-0306-0483
Cub Yellow	718-0306-0498
MTD Red	718-0306-0638
Oyster Gray	718-0306-0662
Yardman Yellow	718-0306-0674