


Service Kit 753-0707

CODE: ST-141

DATE: August 29, 1997

SUBJ: Track cable control

Install Service Kit 753-0707 when replacing cable control part number 746-0900.



Ref. No.	Part No.	Description	Qty.
1	746-0948	Steering track cable	1
2	746-0950	Control trigger	1

Form No. 770-0809A