

# Service Kit

## 753-0880


CODE: CP-038

DATE: September 23, 1999

SUBJ: Replacement Logsplitter Gear Pump &  
Flexible Coupler

② 2-8-00

Use this Service Kit when replacing part number 718-0477 Gear Pump- 16 GPM.



REF NO.

### SERVICE KIT 753-0880 CONSISTS OF:

Part No.	Quantity	Description
718-0684	1	Gear Pump- 16 GPM
718-0685	1	Flexible Coupler- 7/16" ID (Pump Side) & 1.0" ID (Engine Side)