

# Service Kit


CODE: T-148

DATE: November 4, 1999

## 753-0882

SUBJ: Replacement Differential Axle Assembly  
For 2-Speed Transmissions

Use this Service Kit when replacing part number 618-0228 Differential Axle Assembly.



### SERVICE KIT 753-0882 CONSISTS OF:

<u>Reference No.</u>	<u>Part No.</u>	<u>Quantity</u>	<u>Description</u>
1	618-0368	1	Differential Axle Assembly
2	618-0365	2	Hub Assembly- Wheel
3	712-1329	2	Hex Nut 3/4-26