

# Service Kit 753-0887

CODE: T-155

DATE: May 24, 2000

SUBJECT: Shift Lever Replacement

AFFECTED MODELS: Series 820-829 and 840-849  
Garden Tractors with 747-0639A  
Two Speed Shift Lever

Use this Service Kit when replacing 747-0639A Shift Lever.

REF NO.	PART NO.	QTY.	DESCRIPTION
1	747-0981	1	Two Speed Shift Lever
2	718-0504	1	Shift Lever Insert
3	718-0505	1	Shift Cover

**NOTE:** The Hex Screws 710-0642, quantity 3, used to mount the Shift Cover can be reused. The Shift Boot, 721-0450, can also be reused. (See Below)

