

# Service Kit 753-0905


CODE: R-466

DATE: July 9, 2001

SUBJECT: Replacement Engine Pulley

Use this Service Kit when replacing pulley number 756-0551.

| REF. NO. | PART NO.  | DESCRIPTION          |
|----------|-----------|----------------------|
| 1        | 756-1182A | Pulley               |
| 2        | 750-0956  | Spacer               |
| 3        | 710-0561  | Bolt 7/16-20 x 2.50" |



Form No. 770-1880A  
(7/01)

# Service Kit 753-0905


CODE: R-466

DATE: July 9, 2001

SUBJECT: Replacement Engine Pulley

Use this Service Kit when replacing pulley number 756-0551.

| REF. NO. | PART NO.  | DESCRIPTION          |
|----------|-----------|----------------------|
| 1        | 756-1182A | Pulley               |
| 2        | 750-0956  | Spacer               |
| 3        | 710-0561  | Bolt 7/16-20 x 2.50" |



Form No. 770-1880A  
(7/01)